REPORT

DUPLICAIL

TRUESDAIL LABORATORIES, INC.

STS - MICROBIOLOGISTS - ENGINEERS

RESEARCH DEVELOPMENT

DOUGLAS AIRCRAFT COMPANY Internal Mail Code 211-40 **CLIENT**

3835 Lakewood Boulevard

Long Beac, CA 90846

Monthly Storm Drain Inspection

(January, 1989)

P.O. No.: T & M-23465-C

INVESTIGATION

SAMPLE

FRANKLIN AVENUE TUSTIN, CALIFORNIA 92680 AREA CODE 714 . 730-6239 AREA CODE 213 . 225-1564 CABLE: TRUELABS

DATE

February 9, 1989

RECEIVED

January 17, 1989

LABORATORY NO.

31768

As requested by the CRWQCB for NPDES permit numbers CA0001406 and CA0001414

RESULTS

A representative of Truesdail Laboratories, Inc. tested the strom drain discharge on January 17, 1989 at the Douglas, Long Beach (003) and Torrance facilities. The discharge was tested for flow rate, pH, and temperature. The results are as follows:

Sample I.D.	Date	Time	Flow-gpd	<u>TempOF</u>	pH Units
Long Beach (003)	1/17/89	10:20	184,723	62	85
Torrance	1/17/89	11:00	No Flow		

Respectfully submitted,

TRUESDAIL LABORATORIES, INC.

Luis Perez, Supervisor Industrial Waste

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.